




Spalling repairs for cycle 1 pontoons

September 2012



Spalling repairs in Aberdeen

Phase 1:

Remove and replace concrete and add rebar to ends of longitudinal pontoons T, U and V and at end of interior walls of cross pontoon W.

Phase 2:

Remove and replace concrete and add rebar to center section of cross pontoon W.